

One Daytona Blvd.
Daytona Beach, FL
32114
P: +1 (386) 310-6500

IMSA TECHNICAL MEMO IMPC #19-01

To: All IMSA Michelin Pilot Challenge Competitors
From: IMSA Competition
Date: 20 November 2018
Re: Leader Light and X2 Transponder Loom

To ensure Entrant compliance with IMSA Technical Regulations this Memo serves to clarify the required installation of the X2 Transponder, Leader Lights, and Driver ID Module for the 2019 season, including the ROAR. Installations must be made in accordance with each OEM's approved Series Electronics Declaration, available to each Entrant in mid-December.

The Leader Lights, Driver ID Module, and Looms are available from Motec via the following link:

https://www.milspecwiring.com/IMSA-Michelin-Pilot-Challenge_c_937.html

The X2 Transponder and Mounting Bracket will be available in the coming weeks via the Electronics Order Form at the IMSA Team Portal: <https://competitors.imsa.com/>

The general layout of the looms are as follows:



